

Haney - ?



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5

230 SOUTH DEARBORN ST.

CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF:

OCT 17 1985

EPA Region 5 Records Ctr.

5HS-12



355892

CERTIFIED MAIL #P 557 098 047
RETURN RECEIPT REQUESTED

*0316500003 / Cook Co.
Chicago / Sherwin-Williams
Subpart F*

Michael Nechvatal, Manager
Compliance Monitoring Section
Illinois EPA, DLPC
2200 Churchill Road
Springfield, Illinois 62706

Re: Surface Impoundment Status
Sherwin-Williams Company
ILD 005456439

Dear Mr. Nechvatal:

This is to confirm the status of the above facility's surface impoundments, as discussed with Mark Haney of your staff, on October 2, 1985. The impoundments are regulated units and are required to have a permit under 40 CFR 270 and 264, Subpart K. They are, therefore, also required to do groundwater monitoring in accordance with 35 Ill. Adm. Code, Subpart F, until a final decision is made on the permit application.

In view of Mr. Haney's letter to Sherwin-Williams on June 4, 1985, we are requesting any documented information you have which would show the surface impoundments may not be regulated units. Please furnish the information immediately for our use in determining a course of action.

Sherwin-Williams has been notified to continue their groundwater monitoring program until a final decision has been made by U.S. Environmental Protection Agency on the status of the impoundments.

Please contact Diane M. Spencer, at (312) 886-1484, if you have any questions regarding this matter.

Sincerely,

Edith M. Ardiente

Edith M. Ardiente, P.E.
Chief, Technical Programs Section

cc: Ken Bechely, IEPA

RECEIVED

OCT 21 1985

IEPA-DLPC